

Rec'd
7-28-87

NAME Romaldo Community Water Co.		DATE 5-27-87
LOCATION 5597 W. Camino Cielo, Santa Barbara CA 93105		RECHECK DATE Next Annual
MAILING ADDRESS 5595 W. Camino Cielo, Santa Barbara CA 93105		COMPUTER NUMBER 0668
OWNER/OPERATOR		TIME IN
PROGRAM/ELEMENT	SERVICE	TIME OUT

		MAJOR	MINOR
SOURCE PROT	Sewage	1	///
	Activity	2	3
	Flooding	4	5
	Construction	6	7
	Location	8	9
	SOURCE TREAT	Disinfection	10
Filtration		11	12
Treatment Other		13	14
DISTRIB PROT	Storage	15	16
	Piping	17	18
	Cross-Con. Problem	19	///
OPER	Equip. Maint.	20	21
	Records	///	22
	No Operator	23	24
	Cross-Con. Program	25	26
BACTERIOLOGICAL	Number of Samples Insuff. < 4 Samp.	27	
	Number of Samples Insuff. 4-8 Samp.	28	
	Number of Samples Insuff. > 8 Samp.	29	
	Std. Not Met For < 4 Mo.	30	
	Std. Not Met For 4-8 Mo.	31	
	Std. Not Met For > 8 Mo.	32	
	Pub. Notification Bact.	33	
		34	
SAMPLING PRIMARY CHEMISTRY	Inorg. Insuff.	35	
	Inorg. Std. Not Met Nitrate	36	
	Inorg. Std. Not Met Selenium	37	
	Inorg. Std. Not Met Fluoride	38	
	Inorg. Std. Not Met Mercury	39	
	Inorg. Std. Not Met Arsenic	40	
	Inorg. Std. Not Met Other	41	
	Pub. Notification Inorg.	42	
	Org. Insuff.	43	
	Org. Std. Not Met Required	44	
Org. Std. Not Met Other	45		
Pub. Notification Org.	46		
SECD	Secd. Chem. Insuff.	47	
	Secd. Chem. Std. Not Met	48	
	Consumer Acceptance Not Met	49	
TURB	Turb. Insuff. Chronic	50	
	Turb. Insuff. Interm.	51	
	Turb. Std. Not Met Interm.	52	
	Turb. Std. Not Met Chronic	53	
Pub. Notification Turb.	54		
QUANT.	Permit None Valid	55	
	Source	56	
	Storage	57	
Distribution	58		
Safety inadequate	59		
SYSTEM STATUS: (MARK ONE)			
MAJOR DEF.	<input type="checkbox"/>	MINOR DEF.	<input type="checkbox"/>
		NO DEF.	<input type="checkbox"/>

The marked items represent Health Code violations and must be corrected as follows:

This water system consists of: one well, 256 feet deep, 17 gpm; one 10,000 gallon steel storage tank; one central booster pump (make, model, capacity unknown); one 3,000 gallon steel pressure tank, and 2" galvanized steel and SCH 40 NSF approved PVC. This system serves 13 metered services, approximately 40 people.

An annual inspection was made this date with resident **Joe Davis**. The above ground water system facilities have been refurbished and appear well maintained. However, as per Mr. Davis, due to the age of the distribution pipelines some breaks and leaks have occurred in the recent past. Ruptures and leaks in the water pipelines can result in bacteriological contamination of the water supply (Note: Unsatisfactory bacteriological samples were obtained in March, April, and May). Deteriorating pipeline must be replaced with approved potable water pipeline as needed. When replacing the pipeline, be sure to maintain a minimum of 1 vertical foot and 10 horizontal feet distance between the water distribution pipeline and any on-site sewage disposal system.

* Please note that follow-up samples to those previously

OFFICE ADDRESS AND PHONE NUMBER	RECEIVED BY: <i>Mailed 7/28/87</i>
	SANITARIAN: <i>Nancy R. Weber</i>
	PAGE 1 OF 2

© no *Archie* *Archie G.* *Hyatt*

